



Drill pilot holes and mount screws through the shroud/molding

